



---

## SISPM1040-384-LRT-C Release Notes

**Date: Nov.27, 2019**

**Version: 7.10.2313**

---

### Overview

This release notes covers firmware version v7.10.2313 and MIB file for SISPM1040-384-LRT-C

### Release Changes and Enhancements

#### [New Features & Changes]

=====

- \* Modify topology view right side function key design
- \* Add PoP "Traffic Monitor feature is only available on master switch." Message on All Supported DMS Switches Web UI.
- \* Ignore check FW version.
- \* Revert the syntax change back from DisplayString to IpAddress for the firmware and config server address OIDs.
- \* DMS: add Traffic Monitor features.
- \* PoE Auto Checking Add Max. Reboot Times Feature.

#### [Bugs Fixed]

=====

- \* LLDP: Management Address value of the LLDP packet is MAC, not IP address.
- \* CLI: After clean syslog partition, the switch will crash.
- \* DHCP leaking over PVLAN.
- \* Receiving this message "Secure Connection Failed, it wasn't able to get into the switch using Firefox again.
- \* Web: DMS -> Traffic Monitor page does not have help feature.
- \* NTP: ntp server enter IPv6 address for synchronization, which will cause the switch to automatically reboot.
- \* CPU loading : Use Firefox V68.0.2 to upgrade the firmware, the upgrades window always open, and the CPU loading will reach 99%~ 100% after the firmware upgrade is completed.
- \* Config: Show "% 1 problem found during configuration." When reload config.
- \* Use SNMPc refresh SystemInfoEntry Table interval every 2 sec, and use net-snmp sftp to firmware upgrade at the same time, the switch will crash.
- \* SNMP: Switch repeat the save start thought SNMP, will cause Switch to crash.
- \* Fix memory crash in snmp trap.
- \* Add vlan/ntp server setting in CLI, and save config thought web, the setting cannot be saved to startup-config.



Transition Networks  
10900 Red Circle Drive  
Minnetonka, MN55343  
[www.transition.com](http://www.transition.com)

---

- \* SNMP: When setting up firmware upgrade via SNMP, the running-config will automatically add "no snmp-server".
- \* SNMP: Using SNMPc will result in a reduction in free memory.
- \* Web: Execute Restart Device via https, if the browser not close, the switch work abnormal after boot, and CLI work abnormal too, and then ping the switch response time almost 1500ms.
- \* PoE: When Max. Reboot Times set to "0", will be continuously send PoE Auto Checking PD Failure Trap.

### **Known Limitations and Restrictions**

N/A