



SM48TAT4XA-RP Release Notes

Date: Jun.21, 2020

Version: 8.50.0030

Overview

This release notes covers firmware version v8.50.0030 and MIB file for SM48TAT4XA-RP

Release Changes and Enhancements

[New Features & Changes]

=====

- * Add API commands:
 - = api/export_config
 - = api/import_config
 - = api/get_config_action_status
 - = Ping
 - = Get Ping Status
 - = Traceroute
 - = Get Traceroute Status
 - = Activate Config
 - = Auto Power Reset
 - = SNMP trap config
 - = Show syslog
 - = Clear syslog
 - = SFP port details.
- * Add force mode for feeding power to PD without negotiation procedure.
- * Add API + Device list table requirement.
- * Modify name "Non-stop PoE" to "Always-On PoE", and add "Always-On PoE" in mib.

[Bugs Fixed]

=====

- * Access management does not correctly work after restart.
- * SNMP: Trap Destination Port value range need in 1~65535.
- * API: Setting the port config will cause speed_mode show 0,00 and 10.
- * API: Set port speed 100Mbps HDX, then set to Auto, then set to Disabled, speed_mode show 00.
- * PoE: Change poe mode from force mode to enable mode via SNMPc, but value is still force.
- * Mib: PoeConfigurationPortPoEMode value poeplus(2) is superfluous parameter value.
- * API: Can't get PoE firmware version via API.
- * API: No "profile selection" is provided when using API /api/get_poe_config to get PoE schedule.

- * CLI: The description of QCE ipv6 is wrong.
- * EPS: Discrepancy in EPS 'domain' config options between CLI and Web GUI.
- * QoS: Web GUI is allowing 0.0.0.0 mask value in QoS QCE Frame Type IPv4/IPv6 SIP/DIP specific parameter without error message.
- * CLI: QoS config output is coming in 'show run feature ' CLI output.
- * When traceroute the IP address that is not in the same network segment, web UI will be redirected to an error page.
- * Diagnostics: The traceroute results is not consistent between Web and CLI.
- * mib: Use MG-soft to compile mib file, will show one warning.
- * Web: ICMP ping page helper description is not correct.
- * Diagnostics: In Web UI, the Traceroute Max TTL should be set to 255.
- * LLDP: When the switch receives a packet with LLDP-MED, it will send an IEEE802.3 MAC/ PHY packet with two configuration/status TLV.
- * LLDP: When the port speed is 10/100Mbps, the IEEE802.3 MAC/ PHY configuration/status TLV error sent from LLDP.
- * Backup Configuration: Backup Configuration provide download "api_translater.st".
- * LLDP: PMD Auto-Negotiation Advertised Capability field does not display all the available speeds of the port.
- * API: User get wrong information via /api/get_firmware_upgrade_status API.
- * No response from API if changing IP address.
- * MIB: Failed to get the SystemInfoProductionDate value, but got the unparsed mib node.

Known Limitations and Restrictions

N/A