



SM48TAT4XA-RP Release Notes

Date: Dec.9, 2019

Version: 8.40.1553

Overview

This release notes covers firmware version v8.40.1553 and MIB file for SM48TAT4XA-RP

Release Changes and Enhancements

[New Features & Changes]

-
- * Change port-security command description
 - * Restore the traffic monitor function as a standard feature.
 - * Add Click Save Button when Save Start Button on Web UI.
 - * Add PoP “Traffic Monitor feature is only available on master switch.” Message on All Supported DMS Switches Web UI.
 - * Modify topology view right side function key design.
 - * Add ACE MAC bits mask on MAC address fields function requirement.

[Bugs Fixed]

-
- * CLI: Run command "reload defaults" would show error.
 - * CLI: Error message appears during startup.
 - * The switch supplies power to PD device during startup.
 - * Web: LACP key error message is wrong.
 - * MEP: when cPriority is set to 7, it will cause the mep state in the mep instance to fail.

Known Limitations and Restrictions

N/A