



---

## SM24DP4XA Release Notes

**Date: Jun.9 2020**

**Version: 7.10.2544**

---

### Overview

This release notes covers firmware version v7.10.2544 and MIB for SM24DP4XA

### Release Changes and Enhancements

[New Features & Changes]

=====

\* Set the value of timeout WEB GUI

[Bugs Fixed]

=====

\* 10G: When switch port speed mode set to 10G FDX then use 10G(DAC-10G-SFP-01M) cable to connect other 10G switch port (10G FDX mode), the link will fail.

\* VLAN: vlan membership information and selection are inconsistent on WEB and CLI.

\* CLI: When idle time (auto logout time) is reached, Web page does not automatically go to login screen.

\* Syslog: The first syslog sent by the switch is incorrect.

\* TACACS: Set telnet auth method to tacacs, then login through telnet, the "show logging" still display local method.

\* Web: After the user login and logout, the auto logout time does not return to default value (10min).

\* CLI: Performing the "no hostname" command, the hostname does not restore to default.

### Known Limitations and Restrictions

- 1- In order to use DHCP on the SM24DP4XA management port, the port need to be added to PVLAN 1.
- 2- On the SM24DP4XA, Rapid Ring roles cannot be returned to Disable using the Web GUI. The roles can be disabled using the CLI command interface.
- 3- Web timeout has issue with timeout set greater than 10 minutes.