



SISPM1040-3248-L Release Notes

Date: Sep.14, 2020

Version: 8.40.1845

Overview

This release notes covers firmware version v8.40.1845 and MIB file for SISPM1040-3248-L

Release Changes and Enhancements

[New Features & Changes]

=====
* Timeout expected behavior.

[Bugs Fixed]

=====
* Switch crash if DMS master changes frequently.
* Reflash the Web GUI, the Timeout setting will be returned to the value in Startup Config setting.

Known Limitations and Restrictions

1. ERPS: UP MEP is not supported for sub-ring