



**20195F**

## CPSVT100-100 V.35 High Speed Serial

### SOFTWARE VERIFICATION & FUNCTIONALITY REPORT

Rev.	Description	Date	Prepared By
A	Original code	12/11/02	Gary Paulak
B	HW settings saved to config. HW->SW retains switch settings.	01/09/03	Gary Paulak
C	Fixed power up initialization by removing bias read from conv_int().	06/04/04	Gary Paulak
D	Fixed loopback in Hw/Sw mode and Hw display when in Sw mode.	05/23/08	Gary Paulak
E	Fixed remote management channel data corruption. Optimized code using the -105 as a model. Remote copper link status now displays properly. Management to the remote unit is not lost when the remote copper link goes down.	02/08/13	Gary Paulak
F	Fixed the speed dial	3/10/14	Gary Paulak/Bill Revering

Approved by	Department	Signature	Date
Gary Paulak	Engineering	<u>Gary Paulak</u>	<u>3/10/14</u>