



Transition Networks
10900 Red Circle Drive
Minnetonka, MN 55343
www.transition.com

SDSTX3110-12x-LRT-B Release Notes

Date: Feb.3, 2017

Version: 1.4

Overview

This release notes covers firmware version v1.4 for SDSTX3110-121-LRT-B and SDSTX3110-124-LRT-B.

Release Changes and Enhancements

1. Fixed webpage hangs after changing any serial configuration
2. New add info_mp page
3. Fixed reset default not responding

Known Limitations and Restrictions

1. After a Virtual COM has been mapped to a port, changes to the serial settings of that port (example RS232 -> RS422) should not be made.