



SM24DP4XA Release Notes

Date: Jan.31 2020

Version: 7.10.2404

Overview

This release notes covers firmware version v7.10.2404 and MIB for SM24DP4XA

Release Changes and Enhancements

[New Features & Changes]

=====

- * Display System Name on Web Browser Tab

[Bugs Fixed]

- =====
- * SNMPWALK happens timeout at Sm24dp4xaSFPInfoPort OID.
 - * Smilint scan the private mib, many syntax errors were detected
 - * Switch cannot issue DHCP IP other than VLAN 1.

Known Limitations and Restrictions

1. The copper SFPs TN-GLC-T and TN-GLC-T-MG are not supported on the 10G SFP+ slots.