



## SM24DP4XA Release Notes

Date: Sep.23 2020

Version: 7.10.2679

### Overview

This release notes covers firmware version v7.10.2679 and MIB for SM24DP4XA

### Release Changes and Enhancements

#### [New Features & Changes]

- \* Unified API.
- \* Add RADIUS and TACACS Key encryption in Running Config.
- \* Web GUI timeout setting.

#### [Bugs Fixed]

- \* Web: The "Yes" button on the "Restart Device" page cannot be used.
- \* API: Setting Vlan Config via api, the allowed\_vlan set to "1-10,400-4094",but get "1-10%2C400-4094" via API.
- \* API: Setting ip address/dhcp/fallback/ip via api/set\_ip\_address, the interface does not has fallback timer.
- \* Web: Setting radius/tacacs config(key is not encryption)and reboot, the CLI will show Error: HTTPD cache has no valid entry!
- \* Web: Setting radius/tacacs config(key is encryption), the CLI will show Error: HTTPD cache has no valid entry!.
- \* API: get\_port\_config and set\_port\_config returns media is "cooper"
- \* API: set\_mirror\_config does not exactly apply configuration to the switch.
- \* API: The reply JSON format of "device\_list\_table" doesn't a beautifier.
- \* RING: When managing Rapid Ring from the Web interface, it can be enabled on a port but cannot be disabled.
- \* config: When VLAN 1 is disabled, the switch will be abnormal.

### Known Limitations and Restrictions

n/a